



PUBLIC NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date of Public Notice: June 12, 2024

Notice #: CCBFTR02229

Carrier Name and Address : FRONTIER FLORIDA LLC DBA Frontier Communications of Florida
 1919 MCKINNEY AVE, DALLAS TX 75201

Contact: **Your Account Manager** or
 For Technical Issues:
 Howard Saltzman Sr Network Engineer
 Email: Howard.Saltzman@ftr.com
 Phone: 469-899-4578

Implementation Date: Upon FCC approval, with the project completion targeted on or after April 1, 2025

Frontier Florida LLC Inc DBA Frontier Comm. Of Florida announces it intends to retire its Tampa CS2K switch listed below:

Wire Center	Address	CLLI
Tampa FL	610 N Morgan St., Tampa, FL 33602	TAMPFLXA03T

On or after April 1, 2025 the Tampa FL VTOA Tandem switch will be retired and removed from the Frontier network as part of ongoing efforts to modernize the network. All of the NPA/NXXs Codes subtending to the sixty-nine (69) Frontier end offices (see Table B below) supporting Local/Intra-Lata traffic via the Tampa FL VTOA Tandem switch will be moved to the Tampa FL O2T Tandem switch (see details in Table A below). The codes will be rehomed upon decommissioning of the Tampa FL VTOA switch and will be reflected in the Local Exchange Routing Guide (LERG) for the Tampa FL O2T Tandem switch. This will occur on or after April 1, 2025.



Description of Reasonably Foreseeable Impact of the Planned Changes:

The Tampa FL 02T Tandem switch will be the recipient office of traffic migrated from the Tampa FL 03T VTOA Tandem switch. Traffic bound for the end offices listed in Table B will be delivered via the Tampa FL 02T Tandem (TAMPFLXA02T). After all traffic is migrated off of the Tampa FL VTOA Tandem switch, this switch will be retired and removed from the network.

Table A

	FROM	TO
Entity	Tampa 03T VTOA Tandem	Tampa 02T DMS200 Tandem
CLLI	TAMPFLXA03T	TAMPFLXA02T
Product	VTOA CS2K	DMS200
Location	610 N Morgan St., Tampa FL 33602	610 N Morgan St., Tampa FL 33602
Point Code	240-149-095	240-149-094
NXX Type	EOC	EOC
OCN	328	328
Rate Center	Multiple	Multiple
LATA	952	952
State	FL	FL



Table B
Description of Reasonably Foreseeable Impact of the Planned Changes (cont.):

Switch CLLI	Switch Name
ABDLFLXA96H	Auburndale
ALTRFLXARSA	Alturas
ANMRFLXA77H	Anna Maria
BARTFLXA53H	Bartow
BAYUFLXA54H	Bayou
BBPKFLXARSA	Babson Park
BRBAFLXA75H	Bradenton Bay
BRJTFLXARSA	Bradley
BRTNFLXX74H	Bradenton Main
CLWRFLXA44H	Clearwater Main GTD5
CLWRFLXADS0	Clearwater Main 5ESS
CLWRFLXAPS0	Clearwater Main Metasw
CNSDFLXA79H	Countryside
CYGRFLXA32H	Cypress Gardens
DNDNFLXA73H	Dunedin
DUNDFLXA43H	Dundee
ENWDFLXA47H	Englewood
FHSDFLXA57H	Feathersound
FHSDFLXARS0	Feathersound ORM
GNDYFLXA57H	Gandy
FRSTFLXA63H	Frostproof
HDSNFLXA86H	Hudson
HGLDFLXA64H	Highlands
HNCYFLXA42H	Haines City Main
HNCYFLXA424	Haines City North
INLKFLXARSA	Indian Lake
INRKFLXX59H	Indian Rocks
LGBKFLXA38H	Longboat Key
LKALFLXA95H	Lake Alfred
LKLDFLXA68H	Lakeland Main
LKLDFLXE66H	Lakeland East
LKLDFLXN85H	Lakeland North
LKWFLFLXA67H	Lake Wales Main
LKWFLFLXARSA	Lake Wales East



Carrier Customer Bulletin

FRONTIER COMMUNICATIONS PARENT, INC
 1919 MCKINNEY AVE
 DALLAS TX 75201

(Cont'd)

Switch CLI	Switch Name
LLMNFLXADSO	Lealman
LRGOFLXA58H	Largo
MLBYFLXARSA	Mulberry
MNLKFLXA85H	Moon Lake
MYCYFLXA32H	Myakka
NGBHFLXA39H	North Gulf Beach
NPRCFLXA84H	New Port Richey
NRPTFLXA42H	North Port
NRSDFLXA35H	Sarasota Northside
OSPRFLXA96H	Osprey
PKCYFLXARSA	Polk City
PLMTFLXA72H	Palmetto
PLSLFLXA79H	Palma Sola
PNLSFLXA53H	Pinellas GTD5
PNLSFLXADSO	Pinellas 5ESS
POINFLXARSA	Poinciana
PRSHFLXARSA	Parrish
PSDNFLXA34H	Pasadena
SARKFLXARSA	St. Armands Key
SEKYFLXA34H	Siesta Key
SGBEFLXA36H	South Gulf Beach
SKWYFLXADSO	Skyway
SNSPFLXA37H	Seven Springs
SPBGFLXA89H	St. Petersburg Main
SPBGFLXS86H	St. Petersburg South
SPBGFLXADSO	St. Petersburg 5ESS
SPRGFLXA37H	Sarasota Springs
SRSTFLXA95H	Sarasota Main GTD5
SRSTFLXADSO	Sarasota Main 5ESS
SSDSFLXA92H	Sarasota Southside
STGRFLXA78H	St. George
TRSPFLXA93H	Tarpon Springs
VENCFLXA48H	Venice Main
VENCFLXSDSO	Venice South
WNHNFLXC29H	Winter Haven



CLECs, IXC, IECs, wireless carriers, and paging carriers will need to secure new trunk groups built to the Tampa FL 02T Tandem switch or have existing trunk groups to that switch augmented. Most, if not all, carriers already have trunking to the Tampa 02T tandem that may be able to be utilized. Carriers that are code holders with connectivity in the Tampa FL VTOA Tandem switch will be required to reposition the codes to the Tampa FL 02T Tandem switch.

All ASRs for the Tampa FL 02T Tandem switch must be received no later than January 1, 2025 to provide sufficient time to migrate the traffic described above. All traffic must be moved by April 1, 2025. All ASRs for the Tampa FL 02T Tandem switch must carry the project code of **TAMPFLXA03T**.

Please adhere to industry standards using normal procedures that pertain to updates and changes to the LERG for all NXXs subject to the retirement of the Tampa FL VTOA Tandem switch.

For inquiries related to the proposed network reconfiguration, or to arrange a meeting with Frontier Network Engineering and Planning personnel, please contact your Frontier Account Manager. For Network Engineering questions, contact Howard Saltzman, Frontier Voice Engineering, at howard.saltzman@ftr.com or 469-899-4578.

We look forward to working with your team to enable uninterrupted service during the network redesign and transitioning of your traffic.

For further assistance, please contact your Frontier Account Manager.

Public Notice Available on our website at:

<https://wholesale.frontier.com/notifications-and-news>